





Gardens Home, Management

HOA

Hope this Homewatch report finds you well!!! If there is anything you need please let us know and we are more than happy to assist you!! Thank you !!!!

Palm Beach Gardens - Ballenisles
Propert, 9123 N Military Trail Suite 216
Costranes Gardens Home, Management
Inspector Christine Jinotti
Inspector O3/06/2023 10:30:00 AM
Institution O6/07/2022

06/09/2022

....

INTERIOR OF HOME

To enlarge photo in Home Watch report click on photo

Alarm Panel working properly?

Okay

Photo



Kitchen: Picture of entire kitchen including ceilings. Checking for Roof leaks or Water Intrusion

Okay

Photo



Kitchen: Check Fridge and freezer operation

Okay

Photo



Kitchen: Run water in sink & Run disposal

Okay

Photo



Check Pantry for bugs and open items

Okay

Photo



Picture of all thermostats in

Okay

Photo



Wine Cellar/Cooler Record Temps/Picture of thermostat

Okay

Photo



Family Room: Check all Windows/sliders, must be locked and no water intrusion

Okay

Photo



Family Room: Overall Picture including ceilings. Checking ceiling for any Roof leaks or water intrusion

Okay

Photo



Master Bedroom: Check windows/ doors make sure locked & no water intrusion

Okay

hoto



Master Bedroom Closet: Check for leaks or water intrusion

Okay

Phot



Master Bedroom: Picture of Bedroom including ceiling. Checking for roof leaks and water intrusion

Oka

Photo



Master Bathroom: Picture of Bathroom including ceilings. Checking for roof leaks and water intrusion

Okay

Photo



Master Bathroom: Run all faucets, showers & Flush toilets

Okay

hoto





Master Bathroom: Picture of closet & ceiling. Checking for roof leaks and water intrusion

Okay

Photo



Bathrooms & Closets: Picture of room & ceiling. Checking for roof leaks/water intrusion

Okay

Photo





Photo

noto

Bathroom/Guest Flush

Toilets, Run sinks & showers.

Check under sinks for leaks

Powder Room: Picture of Powder Room including ceilings. Checking for roof leaks or water intrusion

Okay

Photo



Powder Room: Flush toilet & Run Faucet

Okay

Photo



A PARTIE OF



Butler /Pantry Area Comments

Pantry all is ok

Okay

Photo



Laundry Room : Washer and dryer are unplugged

Okay

. . . .



Office: Picture of office and ceilings. Checking for water intrusion or roof leaks

Okay

Photo



Dining Room: Picture of Dining Room including ceilings. Checking for Roof leaks and Water intrustion

Okay

Photo



Gym Picture of gym & ceiling checking for roof leaks/water stains

Okay

Photo



Overall Comments

Home is all ok

Okay

hoto



EXTERIOR OF HOME

To enlarge photo in Home Watch report click on photo

External: Picture of mail

Okay

Photo



Picture of front of house

Okay

hoto



Garage: Start car, picture of odometer

Okay

Photo



Garage: Picture of Water heater

Okay

Photo



Garage: Picture of Breaker Panel

Okay

Photo



Report any visible broken roof tiles/shingles/torn soffit screens

Okay



Check soffit screens around house, make sure all in tact

Okay

Photo





Garage: Door from garage to house - locked

Okay

Photo



Report any obvious mildew build up on patio/deck

Okay

Photo



Report any obvious mildew build up on Driveway

Okay

Photo

Report on landscape /any broken sprinkler heads and any obvious concerns

Okay

Photo

Report condition of the pool/spa

Okay

Photo

Report condition of the pool/spa

Okay

Pool Heater off

Okay

Dhata

Picture of Generator

Okay

Dhat

Check under hood of grill

Okay

Dhata

Photo











Run faucet in outdoor sink

Okay

Photo





Garage: Do trash cans need to be emptied or cleaned?

Okay

Photo



Picture of Main Water Valve off upon completion of Homewatch

Okay

Photo



Report any insect infestation next to house

Okay

Photo





Garage: Comments

AC unit in garage working All is good in garage

Okay

Photo





2000